

DATE

TOP SECRET

TO :

ROUTING

FROM :

ACTION:

INFO :

IN 73571

TO

FILE

INFO

CITE

TOP SECRET 100230Z CITE [] 2223

PRIORITY [] INFO []

25X1

25X1

A. BX 6732

B. INS - FILM CORRELATION REPORT

C. INS 010

D. 1. SATISFACTORY

2. FILM DATA BLOCK WAS RECORDING HIGHER THAN THE INS TAPE
THROUGHOUT MISSION BY A CONSTANT 12 MINUTES. *of Lat*

3. FILM DATA BLOCK WAS RECORDING HIGHER THAN THE INS TAPE
THROUGHOUT MISSION BY A CONSTANT 14 MINUTES. *of Long*

4. SATISFACTORY

5. SATISFACTORY

6. SATISFACTORY

7. SATISFACTORY

8. FILM DATA BLOCK WAS RECORDING LOWER THAN THE INS TAPE
THROUGHOUT MISSION BY A CONSTANT 532 KNOTS.

9. SATISFACTORY

10. FILM CLOCK WAS RECORDING 1 SECOND HIGH THROUGHOUT MISSION.

TOP SECRET

GROUP 1
EXCLUDED FROM AUTO-
MATIC DOWNGRADING
AND DECLASSIFICATION

25X1A

IN 73571

TOP SECRET

PAGE 2

E. ALTHOUGH THERE WERE DIFFERENCES BETWEEN THE FILM CLOCK AND THE INS TAPE A SATISFACTORY CORRELATION HAS BEEN ACHIEVED ON THE MISSION.

TOP SECRET TOR / 100242Z NOV 67

*Control drum inadvertently turned off during preflight
Pilot turned on in climb to A/12.
System lost data bits generated until turn on.
Therefore errors induced are indicated in para
D - 2, 3 & 8.*

TOP SECRET